



10/658105

CGC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of


U.S. Patent No. : 6,940,637 B2
Issued : September 6, 2005
Title : **MULTI-BARRIER PHOTONIC HETEROSTRUCTURES**
Docket No. : BAT 0063 PA/40078.234

Certificate of Corrections Branch

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF MAILING
I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on May 16, 2006.

Sir:



Reg. No. 39,564

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE
UNDER 35 U.S.C. 254 and 37 C.F.R. 1.322

In the matter of U.S. Patent No. 6,940,637 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

Col. 1, Line 9, "10/685,122" should read --10/658,122
Col. 1, Line 16, "Modem" should read --Modern--
Col. 8, Line 1, "bandgup" should read --bandgap--

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

Respectfully submitted,
DINSMORE & SHOHL LLP

By


James E. Beyer
Registration No. 39,564

*Certificate
MAY 23 2006
of Correction*

One Dayton Centre
One South Main St., Suite 1300
Dayton, Ohio 45402-2023
Telephone: (937) 449-6400
Facsimile: (937) 449-6405
JEB/vlh
Encl.

MAY 24 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 6,940,637 B2

APPLICATION NO.: 10/658,105

ISSUE DATE : September 6, 2005

INVENTOR(S) : James E. Toney

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, Line 9, "10/685,122" should read --10/658,122

Col. 1, Line 16, "Modem" should read --Modern--

Col. 8, Line 1, "bandup" should read --bandgap--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Dinsmore & Shohl, LLP

One Dayton Centre

One South Main Street, Suite 1300

Dayton, Ohio 45402

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.***MAY 24 2006**

COPY

PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,940,637 B2

APPLICATION NO.: 10/658,105

ISSUE DATE : September 6, 2005

INVENTOR(S) : James E. Toney

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, Line 9, "10/685,122" should read --10/658,122

Col. 1, Line 16, "Modem" should read --Modern--

Col. 8, Line 1, "bandgup" should read --bandgap--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Dinsmore & Shohl, LLP
One Dayton Centre
One South Main Street, Suite 1300
Dayton, Ohio 45402

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

MAY 24 2006